Update firmware tutorial:

Step 1: Turn on the power of the robotic arm and use the USB cable to connect to the computer (close WlkataStudio in advance, otherwise it will fail)

Step 2: Open the download program XLoader, as shown in Figure 1

Step 3: Select the hex file to download in Hex file

Step 4: Select Mega (ATMEGA2560) in Device

Step 5: Select the corresponding port number in COM port (generally there is only one option)

Step 6: Click Upload to start to update the firmware. After the download is successful, there will be a prompt in the lower left corner, as shown in Figure 2.



图 1



图 2